Instruction – How to work in the cleanroom

Expendable materials and technical difficulties

Dieter Kinzler, 26164

- latex / nitrile gloves: intended to protect samples and machines from the fat of your skin
 - → do not touch gloves with bare skin
- test / indicator paper (pH)
- broken glass
 replace broken glass: e-mail to Dieter
- vacuum cleaner for water
 water pistol / tube damaged ?
- glasses, measuring glasses, pipettes, tweezers, gloves (also for acids), eyeglasses, protective skirts, etc.

Chemicals

Annette Geiger, 26161

- bottles
- boards of chemicals (never store chemicals in the table)
 new kind of chemical (Jürgen Mähnß and Annette Geiger)
- empty bottles / empty resist bottles (small) → clean, dry
- canisters, canister label and hazard identification

Working at chemical tables

Susanne Menzel, 26041, Stefan Jenisch, 26161; (Ilona Schwaiger, 26056)

protective clothing and first aid

never work alone!

- table free, clean, dry?
- label filter paper: chemical, user name, date, time
- use glasses only for intended chemicals and only at the intended table
 - → if the needed glass is missing, you cannot work
- after use: clean bottles with running water and dry them
- check acid gloves before and after use
- to use the chemical later again:
 cap the glass and put it to the back of the table
 otherwise dispose chemicals and clean the glasses
- clean the table before leaving it flush the table bowl (press "Wannenspülung")
- after cleaning: control glasses and table with indicator paper if necessary

Working with machines

List of responsible persons